

H_C88BAFFB762D_20231102_191234.log

Vehicle Identification Number	
Total distance	128080 km
Caesar serial number	
Xentry Diagnostics: version	7.7.3
Xentry Diagnostics: data version	09/2023 (2023-07-29)
Operation mode	
India equipment number	C88BAFFB762D
ID of the diagnosis session	No station/session ID found.
Language	al
Logfile name	
Time stamp log file creation	2023-11-02T19:12:36+01:00
Duration of the diagnostic session	
Number of short tests	2

Installed addon versions:	
---------------------------	--

Quicktest1

Sequence Number	1
Quicktest start time	2023-11-02T19:12:36+01:00
Quicktest duration	ERROR Parsing Date
Number of control units	11

CR - CR Common Rail				F
MB hardware part number	6121530379	Diagnostics ID	0/131	
Hardware version	14.2000	Hardware supplier	Bosch	
Value	Text			Status
P1481-008	Glühkerzenausfall - Zylinder 4 (Text Id:32)			CS
P1481-016	Glühkerzenausfall - Zylinder 5 (Text Id:34)			CS
P2204-001	Externer Mengeneingriff durch Sprintshift - Fehlerspeicher vom Steuergerät {Sprintshift} auslesen. (Text Id:36)			S
P1470-004	Ladedruckregelventil - Leitung hat {#LOGO(MB Pruefzeichen,83)#}. (Text Id:38)			S

C = CURRENT, CS = CURRENTLY SAVED, S = SAVED, NT = NOT TESTED, ND = NOT DEFINED

SSG - SSG Sprintshift-Getriebe				f
MB hardware part number	0255459832	Diagnostics ID	0/2	
Hardware version	36.1999	Hardware supplier	Magneti Marelli	
Value	Text			Status
P2081	Die Hydraulikpumpe ist ausgefallen. (Text Id:48)			S

C = CURRENT, CS = CURRENTLY SAVED, S = SAVED, NT = NOT TESTED, ND = NOT DEFINED

INS - KI Kombiinstrument				i
MB hardware part number	0004468521	Diagnostics ID	7/04	
Hardware version	05.2003	Hardware supplier	VDO	
Value	Text			Status
B1042-000	Die CAN-Kommunikation mit dem Getriebesteuergerät ist fehlerhaft. (Text Id:41)			S

C = CURRENT, CS = CURRENTLY SAVED, S = SAVED, NT = NOT TESTED, ND = NOT DEFINED

WSP - WSP Wegfahrsperre				ok
MB hardware part number	0265451832	Diagnostics ID	0/00	
Hardware version	40.1999	Hardware supplier	Temic	

AB - AB Airbag				ok
MB hardware part number	0004460242	Diagnostics ID	6/01	
Hardware version	12.1996	Hardware supplier	Bosch	

ABS - ABS Antiblockiersystem				ok
MB hardware part number	0004463489	Diagnostics ID	0/07	
Hardware version	25.2000	Hardware supplier	Bosch	

HZR - HZR Heizungsregelung				ok
MB hardware part number	0004463428	Diagnostics ID	1/1	
Hardware version	35.1999	Hardware supplier	Hella	

ZV - ZV Zentralverriegelungsanlage				ok
MB hardware part number	0004461019	Diagnostics ID	0/0	
Hardware version	14.1999	Hardware supplier	VDO	

CAN - CAN-Bus				ok
---------------	--	--	--	----

SG_OHNE_KOMM - Steuergeräte ohne Kommunikation	ok
--	----

SG_NICHT_ERKANNT - Wurden Steuergeräte im Kurztest nicht erkannt?	ok
---	----

Quicktest2

Sequence Number	2
Quicktest start time	2023-11-02T19:14:21+01:00
Quicktest duration	ERROR Parsing Date
Number of control units	11

CR - CR Common Rail				F
MB hardware part number	6121530379	Diagnostics ID	0/131	
Hardware version	14.2000	Hardware supplier	Bosch	
Value	Text		Status	
P1481-008	Glühkerzenausfall - Zylinder 4 (Text Id:95)		CS	
P1481-016	Glühkerzenausfall - Zylinder 5 (Text Id:97)		CS	

C = CURRENT, CS = CURRENTLY SAVED, S = SAVED, NT = NOT TESTED, ND = NOT DEFINED

INS - KI Kombiinstrument				ok
MB hardware part number	0004468521	Diagnostics ID	7/04	
Hardware version	05.2003	Hardware supplier	VDO	

WSP - WSP Wegfahrsperre				ok
MB hardware part number	0265451832	Diagnostics ID	0/00	
Hardware version	40.1999	Hardware supplier	Temic	

AB - AB Airbag				ok
MB hardware part number	0004460242	Diagnostics ID	6/01	
Hardware version	12.1996	Hardware supplier	Bosch	

ABS - ABS Antiblockiersystem				ok
MB hardware part number	0004463489	Diagnostics ID	0/07	
Hardware version	25.2000	Hardware supplier	Bosch	

HZR - HZR Heizungsregelung				ok
MB hardware part number	0004463428	Diagnostics ID	1/1	
Hardware version	35.1999	Hardware supplier	Hella	

SSG - SSG Sprintshift-Getriebe				ok
MB hardware part number	0255459832	Diagnostics ID	0/2	
Hardware version	36.1999	Hardware supplier	Magneti Marelli	

ZV - ZV Zentralverriegelungsanlage				ok
MB hardware part number	0004461019	Diagnostics ID	0/0	
Hardware version	14.1999	Hardware supplier	VDO	

CAN - CAN-Bus				ok
---------------	--	--	--	----

SG_OHNE_KOMM - Steuergeräte ohne Kommunikation				ok
--	--	--	--	----

SG_NICHT_ERKANNT - Wurden Steuergeräte im Kurztest nicht erkannt?				ok
---	--	--	--	----